Exterior	Condition Report				
Location Site	Required Work Landscaping	n/a □	Yes ☑	Note/Comments Remove trees from foundation	\$ Cost 250.00
	Steps/Handrails	n/a □	Yes ☑	Front steps and parking area	\$ 1,050.00
	Service walks	n/a □	Yes ☑		\$ 2,000.00
	Fencing	n/a ☑	Yes □		\$ 
	Parking	n/a ☑	Yes 🗆		\$
	Retaining walls	n/a □	Yes 🗸		\$ 500.00
	Other	n/a □	Yes □		\$ 
	Other	n/a □	Yes □		\$
Garage	Singles: repair	n/a ☑	Yes □		\$
	Shingles: Roof over existing	n/a 🗹	Yes □		\$
	Shingles:Tear off & re-roof	n/a ☑	Yes □		\$
	Gutters/downspouts	n/a ☑	Yes □		\$
	Flashing	n/a ☑	Yes □		\$ 
	Eaves	n/a ☑	Yes □		\$ 
	Siding	n/a ☑	Yes □		\$
	Doors	n/a ☑	Yes □		\$
	Windows	n/a ☑	Yes 🗆		\$
	Slab	n/a ☑	Yes □		\$
	Paint	n/a □	Yes ☑		\$ 
Porches	Electrical	n/a ☑	Yes □		\$
	Other	n/a 🗆	Yes □		\$
	Roof	n/a ☑	Yes 🗆		\$
	Deck-upper	n/a ☑	Yes		\$
	Decklower	n/a 🗹	Yes 🗆		\$
	Steps/handrails	n/a 🗆	Yes ☑		\$ 250.00
	Ceiling	n/a ☑	Yes 🗆		\$ 
	Guardrails	n/a ☑	Yes 🗆		\$ 
	Structural	n/a ☑	Yes 🗆		\$
	Paint	n/a □	Yes 🗹		\$ 600.00
	Other	n/a □	Yes 🗆		\$ 
					·

824 West Pierce Street

Other □

**Scope of Work for Property Located at:** 

2/25/2016

Date:

Property is: Single Family ☑ Duplex □

## House

Chimney	n/a □	Yes ☑		\$ 300.00
Shingles: repair	n/a ☑	Yes □		\$ 
Shingles: Roof over existing	n/a ☑	Yes □		\$ 
Shingles:Tear off & re-roof	n/a □	Yes ☑		\$ 8,700.00
Gutters/downspouts	n/a □	Yes ☑		\$ 1,500.00
Flashing	n/a ☑	Yes □		\$ 
Eaves	n/a □	Yes ☑		\$ 800.00
Siding	n/a _□	Yes ☑		\$ 500.00
Storm Doors	n/a □	Yes ☑		\$ 260.00
Prime ("main") Doors	n/a □	Yes ☑	Incl. cellar door	\$ 1,200.00
Storm Windows	n/a □	Yes ☑		\$ 500.00
Prime ("main") Windows	n/a □	Yes ☑		\$ 1,550.00
Paint	n/a □	Yes ☑	Previously Painted Areas	\$ 4,800.00
Foundation	n/a _☑	Yes □	_	\$
Electrical	n/a ☑	Yes □		\$
Other	n/a □	Yes □		\$
Other	n/a □	Yes □		\$
Other	n/a 🔲	Yes 🗆		\$
Other	n/a □	Yes □		\$ 

Exterior: Estimated Cost:\* \$ 24,760.00
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

	Unit: Entire unit (single family) Upper unit of duplex Required Work			Lower unit of duplex		
Heating		, –	V		Φ.	
	Repair/replace boiler	n/a ☑	Yes 🗆	_	\$	
	Repair radiation	n/a ☑	Yes □	~	\$	
	Repair/replace furnace	n/a □	Yes ☑	Assumed, no access	\$	3,000.00
	Repair ductwork	n/a □	Yes ☑	<u></u>	\$	300.00
	Replace thermostat	n/a □	Yes 🗵		\$	100.00
	Repair/replace grilles	n/a □	Yes ☑		\$	150.00
Electrical	Other	n/a □	Yes ☑	Permit	\$	85.00
Electrical	Repair/replace receptacles	n/a □	Yes ☑		\$	500.00
	Repair/replace switches	n/a □	Yes ☑		\$	500.00
	Repair/replace fixtures	n/a □	Yes ☑		\$	500.00
	Install outlets and circuits	n/a ☑	Yes □		\$	
	Install outlets and circuits	n/a ☑	Yes □		\$	
	Install outlets and circuits	n/a ☑	Yes □		\$	
	Install outlets and circuits	n/a ☑	Yes □		\$	
	Upgrade service	n/a □	Yes ☑	Assumed, no access	\$	2,000.00
	Other	n/a □	Yes ☑	Permit	\$	85.00
Di	Other	n/a 🔲	Yes □		\$	
Plumbing	Repair/replace kitchen sink	n/a ☑	Yes □		\$	
	Repair/replace kitchen sink fauce	en/a <u></u>	Yes □		\$	
	Repair/replace tub	n/a ☑	Yes □		\$	
	Repair/replace tub faucet	n/a ☑	Yes □		\$	
	Repair/replace toilet	n/a □	Yes ☑		\$	300.00
	Repair/replace lavatory	n/a □	Yes ☑		\$	275.00
	Repair/replace lavatory faucet	n/a □	Yes ☑		\$	300.00
	Repair/replace wash tub	n/a □	Yes ☑	Assumed, no access	\$	750.00
	Repair/replace wash tub faucet	n/a □	Yes ☑	Assumed, no access	\$	300.00
	Unclog piping:	n/a □	Yes ☑		\$	150.00
	Repair drain/waste/vent piping	n/a □	Yes ☑		\$	220.00
	Repair water piping	n/a □	Yes ☑		\$	300.00
	Repair/replace water heater	n/a □	Yes ☑	Assumed, no access	\$	1,300.00
	Other	n/a 🗆	Yes ☑	Permit	\$	85.00
	Other	n/a □	Yes □		\$	

					Total Exterior and interior Cost:	Φ	40,745.00
					Total Exterior and Interior Cost:*	\$	40,745.00
					Interior: Estimated Cost:	\$	15,985.00
		n/a □	_Yes			\$	
		n/a □	Yes			\$	
		n/a □	Yes		_	\$	
		n/a □	Yes			\$	
Other	Repair defective	n/a □	Yes	7	_	\$	1,000.00
Floors	•				_		4 000 00
Stairs	Repair defective	n/a ☑	Yes	П		\$	
Handrails	Repair/replace defective	n/a □	Yes	<b>√</b>	Self Help	\$	250.00
	Install smoke/CO alarm: 2nd flr.	n/a □	Yes	7	Self Help	\$	80.00
	Install smoke/CO alarm: 1st flr.	n/a □	Yes	7	Self Help	\$	80.00
riie Salety	Install smoke/CO alarm:bsmt.	n/a 🗆	Yes	<b>V</b>	Self Help	\$	80.00
Fire Safety	Repair or repl. @ defective	n/a □	Yes	<u> </u>	<del></del>	\$	1,000.00
Paint	Danair ar rank @ dafaatir a	n/a 🗆	Voc			ф	1 000 00
Trans, ocining	Repair or repl. @ defective	n/a □	Yes	1		\$	1,400.00
Walls/Ceiling	Repair or repl. locks/latches	n/a □	Yes	1	Self Help	\$	175.00
Doors	Repair or replace doors	n/a □	Yes	7		\$	570.00
Doors	Repair or replace sash	n/a □	Yes	<b>√</b>		\$	150.00
	Replace broken glass	n/a ☑	Yes			\$	
Windows							

Inspected by: Jeremy Belot Date: 2/25/2016

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.